### Meagan Redfern





OCARS Pro@uncc.org

From: Sent: Wednesday, June 15, 2005 3:09 PM

To: Meagan Redfern

Subject: UNCC EMLCFM 2005/06/15 #00334 B0065200-00B NORM NEW

EMLCFM 00334 UNCCb 06/15/05 03:09 PM B0065200-00B NORM NEW STRT LREQ

Ticket Nbr: B0065200-00B

Original Call Date: 06/15/05 Time: 03:08 PM Op: MRE

Locate By Date : 06/17/05 Time: 11:59 PM Meet: N Extended job: N

State: CO County: DENVER City: DENVER

3642 Street: HUMBOLDT ST

Grids: 03S068W26N\* Legal: Y

Lat/Long: 39.768816/-104.970530 39.768816/-104.968736

: 39.766275/-104.970530 39.766275/-104.968736

Type of Work: SOIL EXCAVATION Exp.: N

Boring: N

Location: LOC ENTIRE LOT\*TO INCLUDE ALL EASEMENTS AND CITY PROPERTY

Company : PROJECT RESOURCES INC. Type: OTHR

Caller : MEAGAN REDFERN Phone: (303) 487-0377

Alt Cont: AMY JAMES Phone: (303)487-0377

Email: MREDFERN@PROJECTRESOURCESINC.COM

Done for: EPA/ARMY CORP OF ENGINEERS

Remarks:

Members 360NT3 = 360 NETWORK-TOUCH AMERICA CMSND00= COMCAST - NORTH

Members ICGTL3 = ICG TELECOMMUNICATIONS PCKVEL = XCEL ENERGY-ELEC

TRANSM

Members PCNDU0 = XCEL ENERGY-NORTH DENVER PSND14 = XCEL ENGY--APPT

SCHEDULE-- U

Members QLNCND0= QWEST LOCAL NETWORK (UQ) QLNCND1= QWEST LOCAL

NETWORK

Members SPRN01 = U.S. SPRINT TWTEL1 = TIME WARNER


Members WCG01 = WILTEL COMMUNICATION

You are responsible for contacting any other utilities that are not listed above

including the following tier 2 members not notified by the center:

DNVH20 DENVER WATER DEPT (303) 628-6666 DNVPR1 DENVER PARKS & REC. (303)458-4839DTEO01 DNVR TRAFFIC ENG OPERAT. (720)865-4001

WWMG01 WASTEWATER MGMT DIVISION (303)446-3744



1) 437 - 001- Dwc 13:45 Haxes	100-29-06
2) 437 - 002 - DWC 13:55 HOURS	<i>66-29-0</i> 6
3) 437 - 001-SCC 14005 Hours	• 06-27-06
4)437-002-SCC 14:20 Hours	06-29-06
5)	
6)	



4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: 437-001-DWC Client Project ID: 213001.01 Date Collected: 6/29/06 Date Received: 6/29/06

Lab Work Order: 06-4133 Lab Sample ID: 06-4133-21 Wipe

Sample Matrix:

**METALS** 

Method: SW6010

Prep Method: SW6010

Date Prepared: 6/30/06 Date Analyzed: 7/4/06

Lab File ID: 070306PM Method Blank: MB-10272

**Dilution Factor:** 

Lab Fraction ID: 06-4133-21A

Analytes

CAS Number

Result

LQL

Units

Lead

7439-92-1

U

4.0

µg/WIPE

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range H - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits U - Compound analyzed for but not detected

X - See case narrative

\* -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

Definitions: NA - Not Applicable

LQL - Lower Quantitation Limit

Surr - Surrogate

Print Date: 7/5/06

### Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: 437-002-DWC

6/29/06

Client Project ID: 213001.01 Date Collected: 6/29/06

Date Received:

Lab Work Order: 06-4133 Lab Sample ID:

06-4133-22

Sample Matrix:

Wipe

**METALS** 

Prep Method: SW6010 Method: SW6010

Dilution Factor: Date Prepared: 6/30/06 Lab File ID: 070306PM

Lab Fraction ID: 06-4133-22A Date Analyzed: 7/4/06 Method Blank: MB-10272

Result **Analytes CAS Number** LQL Units

U Lead 7439-92-1 4.0 μg/WIPE

Analyst

Approved

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

\* -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

Definitions: NA - Not Applicable

LQL - Lower Quantitation Limit

Surr - Surrogate



4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: 437-001-SCC Client Project ID: 213001.01 Date Collected: 6/29/06 Date Received: 6/29/06

Lab Work Order: 06-4133 Lab Sample ID: 06-4133-23

Sample Matrix: Soil

**METALS** 

Method: SW6010 Prep Method: SW3050

Date Prepared: 6/30/06 Lab File ID: 070306PM **Dilution Factor:** 

Lab Fraction ID: 06-4133-23A Date Analyzed: 7/3/06 Method Blank: MB-10280

Analytes **CAS Number** Result LQL Units

Lead 7439-92-1 28 5.7 mg/Kg

**Approved** 

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

\* -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

Definitions: NA - Not Applicable

LQL - Lower Quantitation Limit

Surr - Surrogate

Print Date: 7/5/06

### Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: 437-002-SCC Client Project ID: 213001.01 Date Collected: 6/29/06

Date Received: 6/29/06

**Lab Work Order:** 06-4133 **Lab Sample ID:** 06-4133-24

Sample Matrix: Soil

**METALS** 

Method: SW6010 Prep Method: SW3050

Date Prepared: 6/30/06 Lab File ID: 070306PM Dilution Factor: 1

Date Analyzed: 7/3/06 Method Blank: MB-10280 Lab Fraction ID: 06-4133-24A

Analytes CAS Number Result LQL Units
Lead 7439-92-1 25 5.7 mg/Kg

Analyst

IVO Approved

Definitions: NA - Not Applicable

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected


X - See case narrative

\* -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

Print Date: 7/5/06

Surr - Surrogate

LQL - Lower Quantitation Limit



North

South East West • = ;

### LBP Assessment Results

### Strata Environmental Resource

	Site	Component	Substrate	Side	Condition	Color	Floor	Room	Results	Depth Inde	PbC	PbC Error
8/18/2005 10:18			CONCRETE	WEST	CRACKED	PURPLE	FIRST	PORCH	Negative	2.78	0.03	0.03
8/18/2005 10:19	437	EXT. WALL	BRICK	WEST	CRACKED	WHITE	FIRST	OUTSIDE	Positive	5.33	2.7	0.5
8/18/2005 10:20		WINDOW FRAME	WOOD	WEST	CRACKED	WHITE		OUTSIDE		6.95	7.5	1.1
8/18/2005 10:21			CONCRETE	WEST	CRACKED	WHITE	FIRST	OUTSIDE	Negative	10	0.3	0.29
8/18/2005 10:22				SOUTH	CRACKED	WHITE	FIRST	OUTSIDE	Positive	2.57	1.7	0.6
8/18/2005 10:23		WINDOW FRAME	WOOD		CRACKED		FIRST	OUTSIDE	Positive	4.17	12.5	1.5
8/18/2005 10:24	437	EXT. WALL	BRICK	EAST	CRACKED	WHITE	FIRST	OUTSIDE	Positive	3.38	9	1.3
8/18/2005 10:25	437	WINDO FRAME	WOOD	EAST	CRACKED	WHITE	FIRST	OUTSIDE	Positive	5.7	5.6	1
8/18/2005 10:27	437	STEP	CONCRETE	SOUTH	PEELING	WHITE	FIRST	OUTSIDE	Negative	5.14	0.03	0.05
8/18/2005 10:29	437	TRIM	WOOD	SOUTH	CRACKED	WHITE		OUTSIDE		2.51	2.4	0.7
8/18/2005 10:31	437	TRIM	MOOD	WEST	CRACKED	PURPLE	SECOND	OUTSIDE	Negative	3.24	0.6	0.1
1												
* *		,										
Note: Readings a	re in mg	g/cm²		<del></del>			<u> </u>					
				<del></del>								
Painted surfaces	not test	ed were assessed	to be in "inta	ct" cond	ition at time	of site vis	it.			1		<del></del>

# Color Photo(s)

The following pages contain color that does not appear in the scanned images.

To view the actual images, contact the Region VIII Records Center at (303) 312-6473.


# Property ID # 437 / 3642 Humboldt Street



West exposure of house

This spreadsheet performs screening level calculations to estimate the effect of peeling leaded paint on the average concentration of lead in yard soil 3642 Humboldt Street

INPUTS General	Variable Mixing depth in yard	Units cm	House 2 54
<b>33.13. 2.</b>	Mixing depth in yard	inches	1
	Soil density	g/cm3	2.5
	RBC in soil	mg/kg	400
	Bkg in clean fill	mg/kg	50
			Small
House-specific	Area of the exposure unit	m2	100.3353
•	Area of the exposure unit	ft2	1080
	Concentration of lead in paint	mg/cm2	125
	Area of peeling paint	m2	18.95222
	Area of peeling paint	ft2	204
COMPUTATIONS			
	Mass of lead from paint	mg	2.4E+06
	Volume of soil	cm3	2.5E+06
	Mass of soil	kg	6.4E+03
	Incremental concentration	mg/kg	371.8
	Maximum acceptable area of p		17.8
	Maximum acceptable area of p	- , , ,	192.0
DECISION			Not OK



North South East West

Metal I rim/Gutters/Downspouts			Misc Structures/Garage/Fences				
Material	Area	Peel/Chip	XRF (Lead)	Material	Area	Peel/Chip	XRF (Lead)
	* # #			tyre to see			
	<del></del>						

### August 18, 2005

### LBP Assessment Results

### Strata Environmental Resource

R CONCRETE WALL BRICK OW FRAME WOOD OW SILL CONCRETE WALL BRICK OW FRAME WOOD WALL BRICK	WEST WEST WEST SOUTH	CRACKED CRACKED CRACKED CRACKED	WHITE WHITE	FIRST FIRST	OUTSIDE OUTSIDE		2.78 5.33 6.95	0.03 2.7 7.5	0.03 0.5
OW FRAME WOOD OW SILL CONCRETE WALL BRICK OW FRAME WOOD	WEST WEST SOUTH	CRACKED CRACKED	WHITE	FIRST	OUTSIDE		l		
OW SILL CONCRETE WALL BRICK OW FRAME WOOD	WEST SOUTH	CRACKED				Positive	6.95	7.5	4 4
WALL BRICK OW FRAME WOOD	SOUTH		WHITE	FIRST			0.00	7.5	1.1
OW FRAME WOOD		CRACKED		ן וויסווון	OUTSIDE	Negative	10	0.3	0.29
	COLITI		WHITE	FIRST	OUTSIDE	Positive	2.57	1.7	0.6
MALL PRICK	SOUTH	CRACKED	WHITE	FIRST	OUTSIDE	Positive	4.17	12.5	1.5
	EAST	CRACKED	WHITE	FIRST	OUTSIDE	Positive	3.38	9	1.3
O FRAME WOOD	EAST	CRACKED	WHITE	FIRST	OUTSIDE	Positive	5.7	5:6	•
CONCRETE	SOUTH	PEELING	WHITE	FIRST	OUTSIDE	Negative	5.14	0.03	0.0
WOOD	SOUTH	CRACKED	WHITE	SECOND	OUTSIDE	Positive	2.51	2.4	0.
MOOD	WEST	CRACKED	PURPLE	SECOND	OUTSIDE	Negative	3.24	0.6	0.
						1			

### Property ID # 437 / 3642 Humboldt Street



West exposure of house

### **Consent For Access To Property**

#### RIGHT OF ENTRY TO PREMISES

Grantor (the property owner) consents to and authorizes the United States Environmental Protection Agency (EPA) or its authorized representatives, collectively the Grantee, to enter and perform certain environmental response activities upon the following described premises:

Owner's Name:  Lydia M Trujillo (	Phone: 303-292-2637
Addresses of	Address: 3642 Humboldt Street
Properties covered by	Address:
this Agreement:	Address:


#### PURPOSE OF RESPONSE ACTIVITIES

The EPA is requesting access to collect soil samples and remove soil that contains elevated concentrations of arsenic and/or lead and may pose a health hazard. The soil will be removed and the excavated area(s) will be replaced with clean materials and restored. This work is being performed under the Vasquez Boulevard/I-70 Superfund Site remediation program.

An EPA representative will contact the Grantor in-person to discuss the work to be performed. The Grantor will have an opportunity to review and approve the planned soil removal and restoration work before it begins. Once the work is finished, the Grantor will be asked to review the work and confirm that it is complete and meets with the Grantor's approval. Upon completion, the Grantor will receive written documentation from EPA that the property has been remediated.

#### ENVIRONMENTAL RESPONSE ACTIONS

By signing this Access Agreement, the Grantor is granting the EPA, its employees, contractors and subcontractors the right to enter the property, at all reasonable times and with prior notice, for the sole purpose of performing the work. This access shall remain in effect until the work has been satisfactorily completed. The Grantor also agrees to:



### **Property Completion Agreement**

This agreement documents the completion of remedial activities performed on my property. My signature will designate that I am satisfied with the restoration of my property, and that no items are in questions, now, or at any time in the future, except those items listed below, if any.

Property ID: 437		
Property Address: 3/2 42 Hunchold	<i>t</i>	
Owner: Pickola Pruilla		
Phone		
Restoration Items in Question:	•	
Item:		·
Item:		
item:		
Additional Control		
Additional Comments:	•	
· ·	•	· [
	•	
•		
•		
I agree restoration is completed, except as moted		
☐ I do not agree restorațion is completed -		
I agree that the sprinkler system is working properly following reinstallation by contractor		
Suport obille 8-8-05	Warie Gowler	8-8-06
Owner's Signature Date	Contractor's Signature	Date





### U.S. Environmental Protection Agency Vasquez Boulevard I/70 Superfund Site Replacement Certificate

Property Owner	Richard Trujillo			
Property Address	3642 Humboldt St.			
Property Identification Number	437			

Material Removed	Quantity	Unit Price	Replacement Value
Flower bed area (square feet)		\$ 2.50	\$
Trees	1	\$50.00	\$50.00
Itemized shrubs/bushes	24	\$12.00	\$288.00
Total			\$338.00

The acceptance of the replacement certificate and the signature below is full acknowledgement by the property owner that this is a fair and reasonable compensation for plant materials removed during remediation activities, but not planted or installed by the government or it's contractors.

The total amount of \$338.00 has been received by the owner in the form of a replacement certificate, #15177, to be utilized at Paulino's Gardens, 6300 N. Broadway, Denver, CO 80216.

Property Owner's Signature

Date

Contractor's Signature

Date

Property ID:	437	Addre	ess 1:	3642 HUMBOLDT STREET
Remarks:		Addr	ess 2:	
		City:		DENVER
		State	! <b>:</b>	СО
		Zip:		80205
		•		The second secon

Date	Item	Quantity	Unit	Remarks
17-Mar-05	Excavated Area (Estimate)	1693	SF	
17-Mar-05	City Property Area	264	SF	
17-Mar-05	Large Rock (Estimate)	468	SF	
17-Mar-05	Brown Mulch (Estimate)	1225	SF	

### 3642 Humboldt Street ID #437

### Additional Detailed Instructions

- 1. All flowerbeds are coming out in the front and back yard, includes bricks.
- 2. Front yard decorative brick will be removed by the owner
- 3. A section of concrete will be removed and not replaced.
- 4. Brown mulch from the house to the west side of shed
- 5. Large rock from west side of shed to back fence
- 6. Remove concrete pad in backyard.
- 7. Clothesline will be removed and put back.
- 8. 8 inch gap between north side of house and fence no access
- 9. All bushes and tress are being removed.

- Remove obstructions including boats, trailers, vehicles, playscape items, wood piles, dog houses, etc;
- Remove flower bulbs or plants that the Grantor or the Grantor's tenant may wish to save;
- Water and maintain replacement vegetation, including fertilizer application, as necessary subsequent to an initial watering period by EPA, unless watering is restricted by Denver Water Board;
- Abide by health and safety guidance provided by EPA;
- If the property is rented, assist EPA in obtaining tenant approval for access to the property to perform the work if EPA is unable to obtain such access; and
- Allow videotaping and/or photography of the property including exterior and interior areas of buildings.

### AGREEMENT NOT TO INTERFERE

The Grantor agrees not to interfere or tamper with any of the activities or work done, or the equipment used to perform the activities, or to undertake any actions regarding the use of said property which would tend to endanger the health or welfare of the Grantees or the environment, or to allow others to use the property in such a manner.

Should you h Center at (30)		<del>-</del>	ogram, please contact the VI	B/I-70 Command
I grant acces	ss to my proj	perties	I do not grant a	access to my properties
Luhan	I Tuis	13/11/05	-	
Signature		Date	Signature	Date
	_		pling that is required. em that will need to be replac	ced.

Page 2 of 2

PROPERTY INFORMATION			DECISION CRITERIA
Property ID:	437		Target Property? Yes
House Number:	3642		Soil Sampled? Yes
Street:	HUMBOLDT ST		Removal Required? Yes
Address:	3642 HUMBOLDT ST	Find Record	Removal Complete?
Unit:			
ZIP Code:	80205	4	SOIL SAMPLE RESULTS
Neighborhood:	COLE	<b>4</b>	Phase 3A
Zone:	R2		Arsenic Decision Value 26
OWNER INFORMA	TION		Lead Decision Value 402
Owner Name:	LYDIA M TRUJILLO		
Mailing Address:	3642 HUMBOLDT ST	<del></del>	
Mailing City State Zip:	DENVER CO 80205		OTHER SAMPLE RESULTS
			Media Description
			Arsenic
			Lead
		<del></del>	

### Real Property Records

Date last updated: Friday, March 11, 2005

### **3** Real Property Search

If you have a question about the value, ownership, or characteristics of this property, or any other property in Denver, please call the Assessor at 720-913-4162.

View Map/Historic District Listing for this Property
Link to property tax information for this property
Link to property sales information for this neighborhood
Link to property sales information for all Denver neighborhoods

|< << >> >| Current/Total Records: 1291/1338

#### PROPERTY INFORMATION

Property Type: Residential Parcel: 0226212002000

Name and Address Information Legal Description

TRUJILLO,LYDIA M L 5 BLK 13

3642 HUMBOLDT ST HYDE PARK ADD DENVER, CO 80205 RESIDENTIAL

Property Address: Tax District

3642 HUMBOLDT ST DENV

Assessment Information

	Actual	Assessed	Exempt	Taxable
Current Year				
Land	15100	1200		
Improvements	133200	10600		
Total	148300	11800	0	11800
Prior Year				
Land	15100	1200		
Improvements	133200	10600		
Total	148300	11800	0	11800

Style: One Story Reception No.:

Year Built: 1891 Recording Date: //
Building Sqr. Foot: 1,036 Document Type:

Bedrooms: 3 Sale Price:

Baths Full/Half: 1/0 Mill Levy: 64.402

Basement/Finished: 340/0

Lot Size: 3,120



### **Property Access Checklist**

Property ID: 437		☐ WORK	STARTED ON://_	
Property Address: 3642 Humboldt		☐ WORK	COMPELTED ON://	
Property Owner: Pichana trujille	0	Property R	enter:	
Mailing Address:		Home Phon	e:	
3642 Humboldt Danver Calorado	L	Fax:		
Danver Calorado		Cell/Pager:		
Home Phone:		Additional 1	Information:	
Fax:		40 SOD		
Cell/Pager:		NO SPRI	NKLER5	
Notification Letter	Sent: <u>02/</u>	04/05	By: M. Redfeen	
	Signed: <u>63</u>	/11/25	4 10-20-11-11-11-11-11-11-11-11-11-11-11-11-11	
Restoration Agreement	Signed: <u>D3</u>	111.05		
Topsoil Sampling (if applicable)	/	_/	Ву:	
☐ Disposal Sampling (if applicable)	/	_/	By:	
Garden Sampling (if applicable)	//		By:	
Utility Clearance	Called: 05/17/05		By: M. Jowlee map-J. Ruger	
Video/Photos (Before)	On://		Ву:	
☐ Video/Photos (During)	On://		By:	
☐ Video/Photos (After)	On: / /		Ву:	
☐ Video/Photos (30-Day)	On://		Ву:	
Property Completion Agreement	Signed:/	//	By:	
Final Report	Issued:/	' <u></u> '	Ву:	
Air Monitoring (as applicable)				
Community Crew On:/	/_	By:		
Results:				
Community Crew On://_		By:		
Results:				
Community Crew On://_		Ву:		
Results:				



### **Restoration Agreement**

The purpose of this agreement is to provide a mutual agreement as to conditions of property prior to remediation activities. This will also serve as decontamination for the purpose of assuring that restoration activities are completed to the satisfaction of the property owner and the United States Environmental Protection Agency (EPA).

Property ID: 437		
Property Address: 3642	Humboldt St.	
Owner: Richard Trujillo		
Phone:		

On the attached diagram(s) indicate area(s) to excavated and depth of excavation, location of all known utilities, subsurface features, surface structures and landscaping features, access location(s) to be used by contractor, and the direction of North. Indicate distances, depths, material types, etc. Indicate digital photos by referencing the photo-log number with an arrow indicating direction of view.

### Items To Be Removed By Owner Before Start Of Remediation: (Use additional sheets as necessary)

The removal, storage, disposal, and/or return of these items is the Owner's responsibility.

Item:	Dog house decontine adaine Dogs
Item:	Dog house, decorative edgins (Dogs Flower base, world
Item:	
Item:	
Item:	
item:	
ltem:	
Item:	



Item:

### Items To Be Removed By Contractor During Remediation And Not Replaced (Use additional sheets as necessary)

Section of proken walk way & see map & note
Item:
Section of broken walk way & see map & note  Item:  Bricks around Flower Beds in backyard.  Item:  Marking Concrete pad along backfence  Item:
Item:
Startian Concrete pad Mona backfence
Item:
Items To Be Removed By Contractor During Remediation And Replaced
Items To Be Removed By Contractor During Remediation And Replaced (Use additional sheets as necessary)
(Use additional sheets as necessary)  Item:
(Use additional sheets as necessary)  Item:
(Use additional sheets as necessary)  Item:
(Use additional sheets as necessary)  Item:  Back fence for access.  Item:  Clothes/Ine
(Use additional sheets as necessary)  Item:
(Use additional sheets as necessary)  Item:  Back fence fen access.  Item:  Cothes/ine  Item:
(Use additional sheets as necessary)  Item:  Back fence for access.  Item:  Clothes/Ine
Item:  Backfence for access.  Item:  Cothes/Ine  Item:
(Use additional sheets as necessary)  Item:  Back fence fen access.  Item:  Cothes/ine  Item:
Item:    Back fence for access.
Item:  Backfence for access.  Item:  Cothes/Ine  Item:
Item:    Clothes line   Item:   Item:
Item:    Back fence for access.




## Landscape Inventory (Use additional sheets as necessary)

ltem	Quantity	Unit	Description/Explanation
Total Area Of Property To Be Excavated	1693 2449	Square Feet	
Number of trees > 2 inch trunk diameter	ф		
Number of trees < 2 inch trunk diameter	١		
Number of Sprinkler Zones, Control Valves, Timers, Heads, etc.  Attach a sketch of the sprinkler layout.	n P		Zones:
Number of and total size of all gardens / flower beds.	# Of Beds:		Ft <sup>2</sup> Of Beds:
Attach a sketch of relative sizes and locations.	# Of Gardens:		Ft <sup>2</sup> Of Gardens:



ltem	Quantity	Unit	Description/Explanation
Agreed upon value of plant materials not to be replaced by contractor.  Note this value will be used to issue a plant voucher to the property owner.	Total # Of Beds:	\$	Total Ft <sup>2</sup> Of Beds To Be Replaced With Certificate:  12 Rose pulper  12 bushes  1 peach tree
Agreed upon list of plant materials that will be replaced by contractor. Be very specific and detailed.  Include a sketch of were each plant will be placed by the contractor.		Each	Only Use For Plants That Are Being Saved and Replanted
Agreed upon area of property to be replaced with grass sod.  Include a sketch of the area(s) to be replaced with grass sod.	NA	SF	Total Ft <sup>2</sup> Of Sod To Be Laid:
Area of City or County property to be landscaped per their requirements.  Include a sketch of the area (s)	Total Ft <sup>2</sup> :	SF	Sod:  Brown Mulch:  Red Mulch:
Agreed upon area of property to be replaced with mulch.	Total Ft <sup>2</sup> Of Mulch:	SF	Red:



Item	Quantity	Unit	Description/Explanation
Agreed upon area to be replaced rock.	Total Ft <sup>2</sup> Of Rock:	SF	Large:  Medium:  Small (pea gravel):  Driveway Gravel:
Agreed upon area to be replaced with no groundcover.	Total Ft <sup>2</sup> With No Groundcover:		

Additional Comments / Instructions:



				<del></del>
		Additional Comments / In	structions Continued:	
		•		
į				
	NO <000	1/1 EN 5		
ŀ	40 Sprin	K CCIW		
N			ocument interior foundation	on walls and possible
blu	pre-existing damage. E	ner does not want PRI to do By checking this box PRI is	not responsible for any	damage done to the
		ng foundation cracks or fissu	ires.	
	🗹 I agree	I do not agree	1 agree	I do not agree
			_ ^	
	11 14.	lle 3-17-05	- [)	a alala
•	Owner's Signature	Date 3-17-05	Contractor's Signature	Date 011/10.1
	Owner a Dignature	Date	Contractor 5 Signature	pate

### **TARGET SHEET**

## EPA REGION VIII SUPERFUND DOCUMENT MANAGEMENT SYSTEM

DOCUMENT NUMBER: 1050760

	DOCUMENT NUMBER.
SI	TE NAME: VASQUEZ BOULEVARD AND I-70
DO	DCUMENT DATE: 06/29/2006
Dı	DOCUMENT NOT SCANNED ue to one of the following reasons:
	PHOTOGRAPHS
	3-DIMENSIONAL
	OVERSIZED
<b>V</b>	AUDIO/VISUAL
	PERMANENTLY BOUND DOCUMENTS
	POOR LEGIBILITY
	OTHER
	NOT AVAILABLE
	TYPES OF DOCUMENTS NOT TO BE SCANNED (Data Packages, Data Validation, Sampling Data, CBI, Chain of Custody)
DO	DOUMENT DESCRIPTION:
	3 - DVDs OF PROPERTY VIDEO, PROPERTY #437
	· · · · · · · · · · · · · · · · · · ·